



Certificate of Registration

This certifies that the Quality Management System of

Star SU Federal De Mexico

Acceso V Nave 20 No. 115A
Desarrollo La Montana , Querétaro, 76050, Mexico

has been assessed by NSF-ISR and found to be in conformance to the following standard(s):

ISO 9001:2015

Scope of Registration:

Reconditioning services for gear tool cutting maintenance.

The validity of this certificate depends on the validity of the main certificate 62731 Star Cutter Company



Certificate Number: 62731-IS10-C0073464
Certificate Issue Date: 04-NOV-2021
Registration Date: 31-OCT-2021
Expiration Date *: 01-NOV-2024

Jennifer Morecraft,
Senior Managing Director

NSF International Strategic Registrations

789 North Dixboro Road, Ann Arbor, Michigan 48105 | (888) NSF-9000 | www.nsf-isr.org

Authorized Registration and /or Accreditation Marks. This certificate is property of NSF-ISR and must be returned upon request.
*Company is audited for conformance at regular intervals. To verify registrations call (888) NSF-9000 or visit our web site at www.nsf-isr.org