



Certificate of Registration

This certifies that the Quality Management System of

Star SU Federal De Mexico

Acceso V Nave 20 No. 115A
Desarrollo La Montana , Querétaro, 76050, México

has been assessed by NSF-ISR and found to be in conformance to the following standard(s):

ISO 9001:2015

Scope of Registration:

Reconditioning services for gear tool cutting maintenance.



Certificate Number:	C0173270-IS3-C0073464
Certificate Issue Date:	06-AUG-2018
Registration Date:	21-JUL-2018
Expiration Date *:	01-NOV-2021

Carl Blazik,
Director, Technical Operations &
Business Units, NSF-ISR, Ltd.

NSF International Strategic Registrations

789 North Dixboro Road, Ann Arbor, Michigan 48105 | (888) NSF-9000 | www.nsf-isr.org